## E.H.I., INC.

8120 Carter St, # 1807 Overland Park, KS 66204 Phone: 913-602-3865 Fax: 866-884-3639



# SUBJECT PROPERTY: 15400 Perry St

Overland Park, KS 66223

## **REPORT NUMBER:** 071509-15400

**INSPECTION DATE:** 7/15/2009

## INSPECTOR: Chris D. Galo



E.H.I., INC.

4941 Shawnee Dr Kansas City, KS 66106 Phone: 913-602-3865 Fax: 913-273-1405

# INVOICE

**SUBJECT PROPERTY:** 15400 Perry St Overland Park, KS 66223 **REPORT NUMBER:** 071509-15400

## **INSPECTION FEES**

DESCRIPTION	AMOUNT
MECHANICAL + STRUCTURAL + TERMITE INSPECTION	\$375.00
SUBTOTAL	\$375.00
PAYMENT RECEIVED	\$375.00
TOTAL DUE	\$0.00

BALANCE PAID

**SUBMIT PAYMENT TO:** 

## E.H.I., INC.

4941 Shawnee Dr Kansas City, KS 66106 Phone: 913-602-3865 Fax: 913-273-1405

**INSPECTOR:** Chris D. Galo

INSPECTION DATE: 7/15/2009

Date Printed: 7/16/2009

Report #: 071509-15400

Time Printed: 6:22 AM

## E.H.I., INC.

4941 Shawnee Dr Kansas City, KS 66106 Phone: 913-602-3865 Fax: 1-913-273-1405

## HOME INSPECTION CONTRACT

## THIS IS INTENDED TO BE A LEGALLY BINDING CONTRACT...PLEASE READ CAREFULLY.

Client Name & Last Name:

**Client Telephone Number:** 

**Inspected Property Address:** 

15400 Perry St Overland Park, KS 66223

I/We (Client) hereby request a limited visual inspection of the structure at the above address to be conducted by E.H.I., INC (Inspector Chris D. Galo), for my/our sole use and benefit. I/We warrant that I/We will read the following agreement carefully. I/We understand I/We are bound by all the terms of this contract. I/We further warrant that I/We will read the entire inspection report when I/We receive it and promptly call the inspector with any questions I/We may have.

## SCOPE OF INSPECTION

The scope of the inspection and report is a limited visual inspection of the general systems and components of the home to identify any system or component listed in the report which may be in need of immediate major repair. The inspection will be performed in compliance with generally accepted standards of practice, a copy of which is available upon request.

#### OUTSIDE SCOPE OF INSPECTION

Any area which is not exposed to view, is concealed, or is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings, or any other thing is not included in this inspection. The inspection does not include any destructive testing or dismantling. Client agrees to assume all the risk for all conditions which are concealed from view at the time of the inspection. This is not a home warranty, guarantee, insurance policy or substitute for real estate transfer disclosures which may be required by law.

## Whether or not they are concealed, the following ARE OUTSIDE THE SCOPE OF THIS INSPECTION:

Specific components noted as being excluded on the individual systems inspection forms

Private water or private sewage systems

Saunas, steam baths, or fixtures and equipment

Radio-controlled devices, automatic gates, elevators, lifts, dumbwaiters and thermostatic or time clock controls

Water softener / purifier systems or solar heating systems

Furnace heat exchangers, freestanding appliances, security alarms or personal property

Adequacy or efficiency of any system or component

Prediction of life expectancy of any item

Building code or zoning ordinance violations

Geological stability or soils condition

Structural stability or engineering analysis

Termites, pests or other wood destroying organisms

Asbestos, radon, formaldehyde, lead, water or air quality, electromagnetic radiation or any environmental hazards

Building value appraisal or cost estimates

Condition of detached buildings

Pool or spas bodies and underground piping

#### Your inspector is a home inspection generalist and is not acting as a licensed engineer or expert in any craft or trade. If your inspector recommends consulting other specialized experts, client must do so at client's expense.

#### I HAVE READ AND AGREE TO THE ABOVE SCOPE OF INSPECTION

## HOME INSPECTION CONTRACT (Continued)

#### THIS IS INTENDED TO BE A LEGALLY BINDING CONTRACT...PLEASE READ CAREFULLY.

**CONFIDENTIAL REPORT:** The inspection report to be prepared for Client is solely and exclusively for Client's own information and may not be relied upon by any other person. Client agrees to maintain the confidentiality of the inspection report and agrees not to disclose any part of it to any other person. Client may distribute copies of the inspection report to the seller and the real estate agents directly involved in this transaction, but Client and Inspector do not in any way intend to benefit said seller or the real estate agents directly or indirectly through this Agreement or the inspection report.

#### CLIENT AGREES TO INDEMNIFY, DEFEND AND HOLD INSPECTOR HARMLESS FROM ANY THIRD PARTY CLAIMS ARISING OUT OF CLIENT'S UNAUTHORIZED DISTRIBUTION OF THE INSPECTION REPORT.

**SEVERABILITY:** Should any provision of this contract be held by a court of competent jurisdiction to be either invalid or unenforceable, the remaining provisions of this contract shall remain in full force and effect, unimpaired by the courts' holding.

**ARBITRATION:** Any dispute concerning the interpretation of this Agreement or arising from this inspection and report, except one for inspection fee payment, shall be resolved between the parties by BINDING ARBITRATION conducted in accordance with the rules of the American Arbitration Association except that the parties shall select an arbitrator who is familiar with the home inspection industry.

The parties hereto shall be entitled to all discovery rights and legal motions as provided in the Kansas/Missouri Code of Civil Procedure. The arbitrator shall apply the substantive and procedural laws of the States of Kansas/Missouri to all issues submitted in the arbitration proceeding. The award of the arbitrator shall be final, and a judgment may be entered on it by any court having jurisdiction.

**GENERAL PROVISIONS:** This inspection contract, the real estate inspection, and the inspection report do not constitute a home warranty, guarantee, or insurance policy of any kind whatsoever. The real estate inspection and inspection report are not a substitute disclosure for real estate transactions which may be required by law. No legal action or proceeding of any kind, including those sounding in tort or contract, can be commenced against Inspector/Inspection Company, or its officers, agents or employees more than one year after the date of the subject inspection. Time is expressly of the essence herein. THIS TIME PERIOD IS SHORTER THAN OTHERWISE PROVIDED BY LAW.

In the event Client discovers a material defect or other deficiency that was not identified and reported by Inspector, Client shall so notify Inspector in writing and allow Inspector and/or Inspector's designated representative to re-inspect and document the condition(s) of the material defect or deficiency prior to making any repair, alteration or replacement to said material defect or deficiency.

The written report to be prepared by Inspector shall be considered the final and exclusive findings of the Inspector regarding the inspection of the property. Client shall not rely on any oral statements made by the Inspector prior to issuance of the written report.

This Agreement shall be binding upon and insure to the benefit of the parties hereto and their heirs, successors and assigns. This agreement constitutes the entire integrated agreement between the parties hereto pertaining to the subject matter hereof, and may be modified only by a written agreement signed by all of the parties hereto. No oral agreements, understandings, or representations shall change, modify, or amend any part of this agreement.

Each party signing this Agreement warrants and represents that he/she has the full capacity and authority to execute this Agreement on behalf of the named party. If this Agreement is executed on behalf of Client by any third party, the person executing this Agreement expressly represents to Inspector that he/she has the full and complete authority to execute this Agreement on Client's behalf and to fully and completely bind Client to all of the terms, conditions, limitations, exceptions and exclusions of this Agreement.

Client acknowledges that they have read and understood all the terms, conditions and limitations of this contract and voluntarily agrees to be bound thereby and agrees to pay the fee listed above.

NO REPRESENTATION IS MADE AS TO THE LEGAL VALIDITY OR ADEQUACY OF ANY PROVISION IN ANY SPECIFIC TRANSACTION. IF YOU DESIRE LEGAL ADVICE, CONSULT AN APPROPRIATE PROFESSIONAL.

Buyer Signature:		Date:	
<b>Buyer Signature:</b>		Date:	
Inspector:	<u>Chris D. Galo</u>	Date:	7/15/2009

## **KEY REFERENCES/CLAVES DE REFERENCIAS**

This Report lists the systems and components inspected by this company. Items not found in this report are considered beyond the scope of this inspection, and should not be considered inspected at this time.

"APPEAR SERVICEABLE" means that we did not observe conditions that would lead us to believe problems existed with this system or component. The item is capable of being used. Some serviceable items may, however, show wear and tear. Other conditions if applicable, will be noted in the body of the report.

**Significantly deficient systems or components** will be identified as: Not functional / unsafe / worn / near end of lifespan. When in the inspector's opinion, an item is "significantly deficient", the reason will be within the body of the report.

### Please read the entire report for all items .

**Notice:** This report contains technical information that may not be readily understandable to the lay person. Therefore, a verbal consultation with the inspector is a mandatory part of this inspection report. If you choose not to consult with the inspector, this inspection company cannot be held liable for your understanding or misunderstanding of this report's contents. If you were not present during this inspection please call the office to arrange for your verbal consultation.

\* Items that have an asterisk next to them. This item or component warrants additional attention, repair or monitoring.

### (1) Items that have a (1) next to them. The Bracketed Numbers are defined as follows:

(1) Recommended evaluation by a qualified licensed structural engineer / geotechnical engineer.

(2) Recommend further review and repairs as needed by a qualified licensed contractor or specialty tradesman dealing with that item or system.

- (3) Recommend further review for the presence of any wood destroying pests or organisms by qualified Pest Inspector.
- (4) This item is a safety hazard correction is needed
- (5) *Recommend upgrading for safety enhancement. This building may have been constructed before current safety standards were developed.*

D/R Dining Room

- FM/R Family Room
- K/R Kitchen Room
- LD/R Laundry Room
- L/R Living Room
- RC/R Recreational Room
- SN/R Sun Room
- MB Master Bedroom

## **OVERVIEW**

Items outlined at this page are considered to be the most important issues found during the Mechanical & Structural Inspections (Based on Functionality and Safety). We recommend that you read the full report and then draw your own conclusions about the items that you would like the seller of the house to fix. Note: do not forget to read the report comments page at the end of the Inspection Report.

Esta página contiene las cosas más importantes que se han descubierto durante el período de las Inspecciones Estructurales y Mecánicas (Basado en Funcionalidad y Seguridad). Les recomendamos que lean el reporte totalmente y lugo determine cuales son las cosas que le quieren pedir al vendedor de la casa que les arregle. Nota: no se olviden de leer la página de comentarios adicionales del Reporte de Inspección (al final del reporte).

- 1 Attic -- Recommend to seal areas where the furnace flues are venting across the roof (found evidence of prior water penetration).
- 2 Bath # 3 -- Sink: Slow draining (check the drain stopper please).
- 3 Bath # 5 & 6 -- Ventilation: Too much vibration at the exhaust fans.
- 4 Bath # 6 (Bath # 6 is located inside bedroom # 3) -- did not find any issue with this bathroom.
- 5 Ceiling Fans -- Ask the seller where the ceiling fan remote controls are located.
- 6 Ceilings -- Found a few spots where the ceiling paint was applied to the ceiling trims at the Master Bedroom. Patch vertical crack at the ceiling at: Master Bedroom. Replace wood molding at the ceiling at the breakfast area (off the kitchen) -- its has a large size knot.
- 7 Cooling System -- Can not test the Cooling System, temperature is below 60 F.
- 8 Electrical -- Loose outlets at: left and right sides of the kitchen. GFCI outlets are not tripping at the bar area. Provide cover for outlet at: Bath # 5. Apparently the wine chiller is not hooked up (outlet and plug maybe behind the unit, removing this unit is beyond the scope of this inspection) -- ask the seller to show that it is working properly please.
- 9 Exterior Doors -- Minor case of visible daylight at the main entry door. Uneven door jamb (door leading to the deck).
- 10 Exterior Stairs -- Detached slate for the front stair + re-grouting recommended for slates at the front of the house. Exterior Stairs (Back of the Building) --- staining and water proofing recommended.
- 11 Exterior Trims -- Painting recommended for wooden trims at the front of the house (right side of the main entry door area where fake window is located).
- 12 Exterior Walls -- Call an stucco contractor to provide further evaluation and repairs for the orange/corrosion spots at the stucco walls (check the entire perimeter please). It appears that two wooden windows at the left and right sides of the exterior fireplace were ordered too short respect to the frame or a portion of the window at the exterior is missing. Repair exhaust accessory (behind the exterior fireplace) -- area between the two windows.
- 13 Fireplace -- Recommend to remove glue/dirt at the front cover of the fireplace (Living room area). Was not able to ignite the fireplace located at the Dining area (may have air accumulated at the pilot gas line). Recommend to place electrical wire connections inside a junction box at the area below the fireplace (the one off the kitchen).

Garage -- Minor inflation of the vehicle door wood (near the bolts). Peeling paint at the vehicle door wooden trims.

- 14 Garage Door -- Adjustments interior door (striker plate).
- 15 Heating System -- Missing air distribution register at: L/R. Install air register that was covered by the carpet at: BR # 3.
- 16 Interior Doors -- Adjustments recommended for doors leading to the master bathroom (check the balls above the doors). Too much compression at the door hinges at closet (located off Bath # 5) -- see door hinges for locations. Chipped off door at the bottom (master bedroom).

Interior Walls -- Recommend to re-finish taping and painting the drywall at areas that are cracked (Upper level hallway off the seating room, Lower level hallway off the Master Bedroom, Colum at hallway near the main entry door, Master Bedroom closet area near the floor, Master Bedroom closet above the entry door). Patch small holes located at the Master Bedroom walls. Recommend to provide an extension of the wall splash at the left and right sides of the bar sink (off the kitchen area) -- this was requested by the buyer. Recommend to provide edge crown with grout at areas where tiles were installed on the walls (at the kitchen).

Kitchen -- Leaking at sprayer.

- 17 Retaining Walls -- Recommend to build a retaining wall at the front-right corner of the building (lots of soil erosion, surface right now is covered with mulch).
- 18 Roof -- Some shingles were impacted by hail at several places (this is a very common phenomenon in this part of the country) -- keep an eye on hail storms please. Screw head exposed above shingle at the front of the house.
- 19 Roof (Low elevation at the back of the house) -- Missing two shingles (the ones that go above the metal flashings).
- 20 Smoke Detectors -- Make sure that all detectors have batteries that will last at least 1 year.
- 21 Sump Pump -- Unit is not responding (check the switch) + detached elbow at the discharge line.
- 22 Water Supply Line -- Replace garden valve at the right side of the building (the pop up component is trapped within the stucco wall).
- 23 Windows -- Providing screens for all windows.

Date Printed: 7/16/2009

Report #: 071509-15400

STF	UCT	URAL	INSPEC	CTION
••••				

1. Driveway	<b> N/A</b>	Serviceable Settled	Not Functional (1) Raised	Maintenance *	Limited visibility
2. Sidewalk Sealant needed	<b>N/A</b>	Serviceable Settled	Not Functional (1)	Maintenance *	Limited Visibility
3. Retaining Wall Sealant needed See Comments Pag	<b>N/A</b>	Serviceable	Not Functional (1)     Common cracks	Maintenance *	Limited Visibility openings/holes
4. Patio	N/A	Serviceable Settled	Not Functional (1)	Maintenance *     Erosion	Limited Visibility
5. Porch Sealant needed Loose railings	□ N/A	Serviceable     Settled     Missing railings	Not Functional (1) Poor drainage S	Maintenance * Erosion Corroded/Rusted	Limited Visibility Common cracks Railings
6. Deck Loose railings Loose posts	□ N/A	Serviceable     Missing railings     Missing metal			Limited Visibility od boards/Railings building (Nailed)
7. Fences Deteriorated fences	□ N/A	Serviceable     Gates need ad	Not Functional (1) justments	Maintenance * Leaning fences/L	Limited Visibility oose Posts
8. Stairs Sealant needed Loose handrails	□ N/A	Serviceable Settled Missing handra			Limited Visibility Common Cracks roded Post & Rails
			stair + re-grouting re ning and water proof		ates at the front of the house.
9. Exterior Walls		Sunding) Stan	Not Functional (1)	Maintenance *	Limited Visibility
Peeling paint		Siding was fini	— ,,	Wood/Soil Conta	
Common cracks See Comments Pag	e.	Moisture dama	age at wall	Caulking, pasting	a k painting needed
10. Exterior Trims Moisture damage to Maintenance for eave Cracked wall trims		Serviceable Moisture dama Maintenance fo Rotting wall tri	or fascia	Maintenance * Moisture damage Maintenance for Prior patching at	soffits
	ntina rea	-			right side of the main entry
door area where fak	-				
<b>11. Gutters</b> Leaking gutters         Filled with leaves         Loose downspouts	□ N/A	Serviceable Missing gutters	water (not draining)	Maintenance * Sagging gutter (F Corroded/Rusted Extend downspo	
12. Site Grading	N/A	Serviceable	Not Functional (1) oundation walls	Maintenance *	Limited Visibility

## STRUCTURAL INSPECTION

		STRUCTURAL INSPECT	ION
13. Foundation	<b>N/A</b>	Serviceable Not Functional (1)	Maintenance * Jimited Visibility
Several common cracks	s were found a	t the Exterior/Interior Foundation Walls (Fill of	cracks with epoxy)
Dried Water Stains note	ed at the baser	ment floors/walls	Water is entering via cracks at the walls
Major cracks were found	d at the basem	nent Interior/Exterior Walls - Further Analysis F	Recommended (Contact a Structural Engineer)
Walls have shifted Inwa	rd/Outward/Se	ettled - Further Analysis Recommended (Conta	act a Structural Engineer)
Minor settlement		Moderate settlement	Excessive settlement
14. Flooring	<b>N/A</b>	Serviceable Not Functional (1)	Maintenance * Limited Visibility
Uneven surface		Water stains at the floor	Fill Cracks at concrete floor with epoxy
Minor settlement		Moderate settlement	Excessive settlement
	_		
15. Sump Pump	N/A	Serviceable V Not Functional (1)	Maintenance * Limited Visibility
Provide 120V outlet		Missing cover for well	Recommend to install a sump pump at floor
See Comments Page	_		
16. Roof (Main)	N/A	Serviceable Not Functional (1)	Maintenance * Limited Visibility
Moderate wear		Heavy wear	Nearing the end of its useful life
See Comments Page.			
16a. Roof (2nd)	N/A	Serviceable Not Functional (1)	Maintenance * Limited Visibility
Moderate wear		Heavy wear	Nearing the end of its useful life
See Comments Page			
16b. Flashings	□ N/A	Serviceable Not Functional (1)	Maintenance * Limited Visibility
Moderate wear		Heavy wear (Rust/Corrosion)	Add sealant at boundaries between roof/Vent pipes
	_		
17. Chimney	N/A	Serviceable Not Functional (1)	Maintenance *
Rain cap Recommended	Ł	Corroded/Rusted Metal at Top	Add sealant at boundary between roof/chimney
18. Attic		Serviceable Not Functional (1)	✓ Maintenance * ✓ Limited Visibility
Attic Recommend to	seal areas	where the furnace flues are venting	across the roof (found evidence of prior water
penetration).			
18a. Ventilation	N/A	Serviceable Not Functional (1)	Maintenance *     Limited Visibility
18b. Insulation	N/A	Serviceable Not Functional (1)	Maintenance * ⊥imited Visibility
19. Exterior Doors	N/A	Serviceable Not Functional (1)	Maintenance *
Cracked wood moldings	;	Missing piston at storm door	Deteriorated storm door/Heavy Wear
See Comments Page	_		
20. Garage Doors	N/A	Serviceable Not Functional (1)	Maintenance * Limited Visibility
Blocked access		Hollow core door	Deteriorated/Heavy Wear
Garage Door Adjust		or door (striker plate).	
21. Interior Doors	N/A	Serviceable Not Functional (1)	Maintenance * Limited Visibility
Blocked access		Moderate wear	Deteriorated/Heavy Wear
Door rubs frame		Door rubs the floor	Door not latching properly
Missing closet doors		Missing closet door floor tracks	Closet doors deteriorated/Heavy wear
Justanian Daava Allist		was a stand familia and take the state of the state	a stan b athus and (ab a sluth a b alla ab such that

Interior Doors -- Adjustments recommended for doors leading to the master bathroom (check the balls above the doors). Too much compression at the door hinges at closet (located off Bath # 5) -- see door hinges for locations. Chipped off door at the bottom (master bedroom).

Date Printed: 7/16/2009

## STRUCTURAL INSPECTION

<ul> <li>22. Windows</li> <li>Water stains at windows</li> <li>Cracked glass at:</li> <li>Pane not staying up at:</li> <li>Missing ropes/weights at</li> <li>Not latching properly at:</li> <li>Damaged screens at:</li> <li>Windows Providing screens</li> </ul>	t:	Not Functional (1) loss to several windows	<ul> <li>✓ Maintenance *</li> <li>✓ Weather stripping</li> </ul>	Limited Visibility recommended
23. Interior Walls Blocked access Major settlement cracks f	N/A Serviceable Common cra found at several places R	Not Functional (1) acks ecommend to have a structu	Maintenance * Dried water stains ral engineer conduct fur	
Ceilings Found a few	spots where the ceilin ling at: Master Bedroo	ecommend to have a structu ig paint was applied to m. Replace wood mol	the ceiling trims at	ther analysis the Master Bedroom. Patch at the breakfast area (off the Limited Visibility
26. Ceiling Fans         Fan wobbles at:         See Comments Page         27. Stairs         Missing handrails at:	N/A Serviceable	<ul> <li>Not Functional (1)</li> <li>Not Functional (1)</li> </ul>	Maintenance * Maintenance *	Limited Visibility Limited Visibility

## **MECHANICAL INSPECTION**

1. Water Service	□ N/A		erviceable loderate corr		Functional (1)		Maintenance * Heavy corrosion/	Limited Visibility
2. Supply Lines	<b>N/A</b>		erviceable		Functional (1)		Maintenance *	Limited Visibility
Typical wear			loderate corr				Heavy corrosion/	
Water Supply Line R	eplace g	garder	n valve at t	he right	side of the bu	uildir	ng (the pop up	component is trapped
within the stucco wall).	<b>—</b>	<b>—</b> -						
3. Waste Lines	<b></b> N/A	<u> </u>	erviceable		Functional (1)		Maintenance *	Limited Visibility
U Typical wear			loderate corr	osion/rust	(basement)		Heavy corrosion/	rust (basement)
1 Eucl System	<b>N/A</b>		an daaabla				Maintonanaa *	✓ Limited Visibility
4. Fuel System			erviceable		Functional (1)		Maintenance *	Limited Visibility
No gas present at the tir		nspecu		iot inspect	the rue System	1		
5. Water Heater	□ N/A		erviceable	Not	Functional (1)		Maintenance *	Limited Visibility
Typical wear			loderate corr				_ocated at:	Basement
Missing water shut off						-		Dabomont
Missing TPR overflow pi	be							
Rust/Metal Flakes								
Improper flame pattern								
6. Heating	<b>N/A</b>	✓ S	erviceable	Not I	Functional (1)		Maintenance *	Limited Visibility
6a. Air Filter	🗌 N/A	✓ S	erviceable	_	Functional (1)		Maintenance *	Missing
6b. Burners	□ N/A		erviceable		Functional (1)		Maintenance *	Dirty/Metal flakes
6c. Combustion	🗌 N/A	✓ S	erviceable		Functional (1)		Maintenance *	Improper air supply
6d. Venting Flues	N/A	√ S	erviceable	Not I	Functional (1)		Maintenance *	Leaking flue gases
6d. Air Distribution	□ N/A	✓ S	erviceable	Not I	Functional (1)		Maintenance *	Leaking air to surroundings
Heating System Miss BR # 3.	sing air c	listribu	ution regis	ter at: L	/R. Install ai	r reg	gister that was	covered by the carpet at:
7. Cooling	<u></u> N/A	L s	erviceable	Not I	Functional (1)		Maintenance *	Limited Visibility
7a. Low Pressure	<u></u> N/A	∐ s	erviceable	Not I	Functional (1)		Maintenance *	Damaged
7b. High Pressure	<u></u> N/A	L s	erviceable	Not I	Functional (1)		Maintenance *	Missing insulation at lines
7c. Condensate	_∕_ N/A		erviceable		Functional (1)		Maintenance *	Blocked drainage
Can not test the AC system, temperature is below 60 F.								
Cooling System Car	not tes	t the C	Cooling Sy	/stem, te	emperature is	belo	ow 60 F.	
8. Electrical Service	□ N/A	✓ S	erviceable	Not I	Functional (1)		Maintenance *	Limited Visibility
9. Electrical Panel	N/A	□s	erviceable	Not I	Functional (1)		Maintenance *	Limited Visibility
9a. Sub-Panel			erviceable		Functional (1)	$\square$	Maintenance *	Limited visibility
Defects (See overview p					(.)			_ · ·
Label breakers	0,							
9b. Electrical Wiring	□ N/A	🗌 s	erviceable	Not	Functional (1)		Maintenance *	Limited Visibility
Furnishing prevents full								
Original wiring is a two	-				ets).			
Loose outlet/switches at	•		-		-			
Missing cover plates at:								
Missing light fixture cove	ers at:							
See Comments Page.								

## **MECHANICAL INSPECTION**

<b>10. Fireplaces</b> Contact a chimney See Comments Page.	<b>N/A</b> N/A	Serviceable r to conduct are	Not Functional (2) More detailed inspect	Maintenance * ion of the chimney	Limited Visibility system
11. Smoke Detectors Detector not Operational Add more detectors at: Smoke Detectors Mal		Serviceable Bedrooms, hallvat all detectors h	•	✓ Maintenance * last at least 1 yea	Not Accessible
12. Laundry 12a. 120V Outlet 12b. 240V Outlet 12c. Plumbing 12d. Dryer Vent 12e. Gas Piping	<ul> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>✓ N/A</li> </ul>	Basement         Serviceable         Serviceable         Serviceable         Serviceable         Serviceable         Serviceable	Service Area Not Functional (1)	<ul> <li>Kitchen</li> <li>Maintenance *</li> <li>Maintenance *</li> <li>Maintenance *</li> <li>Maintenance *</li> <li>Maintenance *</li> </ul>	<ul> <li>Bathroom</li> <li>Open Ground</li> <li>None present</li> <li>Limited visibility</li> <li>Limited visibility</li> <li>None present</li> </ul>
<ul> <li>13. Kitchen - Cabinets Refrigerators, freezer, micro</li> <li>13a. Cabinets</li> <li>13b. Counters</li> <li>13c. Plumbing</li> <li>13d. Sinks</li> <li>13e. Disposal</li> <li>Kitchen Leaking at spontation</li> </ul>	waves, ice N/A N/A N/A N/A N/A N/A N/A N/A	•	•	Dection Maintenance * Maintenance * Maintenance * Maintenance * Maintenance *	<ul> <li>Limited visibility</li> <li>Limited visibility</li> <li>Limited visibility</li> <li>Limited visibility</li> <li>Limited visibility</li> <li>Limited visibility</li> </ul>
14. Range/Cook top Missing cover for light un	N/A der the hood	Serviceable	Not Functional (1)	Maintenance *	✓ Limited visibility
15. Dishwashing	□ N/A	Serviceable	Not Functional (1)	Maintenance *	Limited visibility
16. Garage - Automatic 16a. Garage Type Automatic Opener Motor Railings/Tracks Vehicle Door Electrical Extension cord used as p Garage Minor inflation	<ul> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> <li>N/A</li> </ul>	<ul> <li>Attached</li> <li>Serviceable</li> <li>Serviceable</li> <li>Serviceable</li> <li>Serviceable</li> <li>Serviceable</li> <li>Serviceable</li> </ul>	Detached Not Functional (1)	None         Maintenance *         Maintenance *         Maintenance *         Maintenance *         Maintenance *         Maintenance *         Maintenance *	Carport Limited visibility Limited visibility Limited visibility Limited visibility Limited visibility Limited visibility

trims.

## **MECHANICAL INSPECTION**

17. Bath Location I Off Max Determining if shower pans are water		☑ 3 Off K e of this ins		∕	1 🗹 5 -	BR # 3
Areas/surfaces not fully visible are ex	cluded from this inspec	tion (i.e. clut	tered areas, be	hind the wa	lls, under carpe	ets, under
<b>18. Toilets</b> Bath # 6 (Bath # 6 is located insi	Serviceable Maintenance* de bedroom # 3) c	✓ 1 □ 1 lid not find	2 2 2 any issue wit	<mark> </mark>	✓ <b>4</b> □ <b>4</b> hroom.	✓ 5 □ 5
,	,					
19. Sinks - Faucet	<ul> <li>Serviceable</li> <li>Maintenance*</li> </ul>	✓ 1 □ 1	✓ 2 □ 2	✓ 3 □ 3	✓ 4 □ 4	✓ 5 □ 5
20. Sinks - Drains	Serviceable	✓ 1 □ 1	✓ 2 □ 2	□ 3 □ 3	✓ 4 □ 4	✓ 5 □ 5
Bath # 3 Sink: Slow draining (	check the drain stop	per please	).			
21. Sinks - Counters/Vanity	Serviceable	✓ 1 □ 1	✓ 2 □ 2	✓ 3 □ 3	✓ 4 □ 4	✓ 5 □ 5
22. Sinks - Cabinets	<ul> <li>Serviceable</li> <li>Maintenance*</li> </ul>	✓ 1 □ 1	✓ 2 □ 2	✓ 3 □ 3	✓ 4 □ 4	√ 5 □ 5
<b>23. Ventilation</b> Bath # 5 & 6 Ventilation: Too	Serviceable     Maintenance* much vibration at the	<ul> <li>✓ 1</li> <li>✓ 1</li> <li>exhaust families</li> </ul>	2 2 2 ans.	✓ 3 □ 3	✓ 4 □ 4	☐ 5 ☐ 5
24. Bathtub - Faucet	<ul> <li>✓ Serviceable</li> <li>✓ Maintenance*</li> </ul>	☐ 1 ☐ 1	✓ 2 □ 2	□ 3 □ 3	✓ 4 □ 4	☐ 5 ☐ 5
25. Bathtub - Drains	<ul> <li>✓ Serviceable</li> <li>✓ Maintenance*</li> </ul>	☐ 1 ☐ 1	✓ 2 2 2	3 3	✓ 4 □ 4	☐ 5 ☐ 5
26. Bathtub - Enclosure	<ul> <li>✓ Serviceable</li> <li>✓ Maintenance*</li> </ul>	☐ 1 ☐ 1	✓ 2 □ 2	3 3	✓ 4 □ 4	5 5
27. Shower - Plumbing	<ul> <li>Serviceable</li> <li>Maintenance*</li> </ul>	☐ 1 ☐ 1	✓ 2 □ 2	□ 3 □ 3	✓ 4 □ 4	✓ 5 □ 5
28. Shower - Drains	<ul> <li>Serviceable</li> <li>Maintenance*</li> </ul>	□ 1 □ 1	✓ 2 □ 2	□ 3 □ 3	✓ 4 □ 4	✓ 5 □ 5
28a. Shower - Enclosure	<ul> <li>Serviceable</li> <li>Maintenance*</li> </ul>	☐ 1 ☐ 1	✓ 2 □ 2	3 3	✓ 4 □ 4	✓ 5 □ 5

## **MATERIALS & TECHNICAL DATA**

		VIA	TERIALS & TECHNIC	JA	LDATA			
Driveway	N/A	$\checkmark$	Concrete		Asphalt		Gravel	
Sidewalk	□ N/A	$\checkmark$	Concrete		Brick		Stone	Gravel
Retaining Wall	🗹 N/A		Concrete		Brick		Stone	
Patio	□ N/A	$\checkmark$	Concrete		Brick		Stone	
Porch	□ N/A	$\checkmark$	Concrete		Wood		Other	
Deck	□ N/A	$\checkmark$	Wood		Stone		Other	
Fences	□ N/A		Wood		Chainlink	$\checkmark$	Iron	
Stairs	□ N/A	$\checkmark$	Concrete	$\checkmark$	Wood		Other	
Exterior Walls	□ N/A		Vinyl/Metal		Wood/Hardiboard		Brick	Stucco
Trims	□ N/A	$\checkmark$	Metal		Plastic	$\checkmark$	Wood	
Gutters	□ N/A	$\checkmark$	Metal		Plastic		Other	
Foundation	□ N/A	$\checkmark$	Concrete		Block		Stone	
Floors	□ N/A	$\checkmark$	Concrete	$\checkmark$	Wood		Other	
Floors - Subfloors	□ N/A	$\checkmark$	Concrete	$\checkmark$	Wood		Stone	
Main Roof	□ N/A	$\checkmark$	Asphalt Shingle		Wood Shakes		Tile	
Second Roof	🗹 N/A		Asphalt Shingle		Metal/Plastic		Asphalt Roll Off	
Chimney - Fireplace	□ N/A		Brick	$\checkmark$	Metal Flue		Wood Casing	
Insulation Type	□ N/A	$\checkmark$	Fiber Glass	$\checkmark$	Blown In		Other	
Windows	🗌 N/A	$\checkmark$	Thermal	$\checkmark$	Wood	$\checkmark$	Metal	
Interior Walls	🗌 N/A	$\checkmark$	Wall Paper	$\checkmark$	Drywall		Plaster	Panel
Ceilings	<b>N/A</b>		Ceiling Tile	$\checkmark$	Drywall		Plaster	Panel
Floors	□ N/A	$\checkmark$	Carpet	$\checkmark$	Wood	$\checkmark$	Vinyl	Tile
Water - Service Line	🗌 N/A	$\checkmark$	Copper		Galvanized		PVC	Other
Water - Supply Lines	□ N/A		Polybutylene		Galvanized	$\checkmark$	PVC/CPVC	Copper
Water - Waste Lines	□ N/A	$\checkmark$	PVC	$\checkmark$	ABS	$\checkmark$	Iron	Copper
Fuel System	□ N/A	$\checkmark$	Gas		Electrical		Solar	Diesel
Water Heater	🗌 N/A	$\checkmark$	Gas		Electrical		In - Line Sys.	
Heating System	<b>N/A</b>	$\checkmark$	Gas		Electrical	$\checkmark$	Forced Air	H-Pump
Cooling System	🗌 N/A	$\checkmark$	Electrical					
<b>Electrical - Service Wire</b>	🗌 N/A		Copper	$\checkmark$	Aluminum		Not Visible	
Electrical - Circuits	🗌 N/A	$\checkmark$	Copper		Aluminum			
Range/Cooktop Hook-up	□ N/A		Electric	$\checkmark$	Gas		Combination	
Kitchen Counter Tops	🗌 N/A	$\checkmark$	Laminate		Stone		Combination	
Laundry - Dryer Hook-up	🗌 N/A	$\checkmark$	Electric		Gas		Combination	
			TECHNICAL DA	ТΑ				
Building Est. Age (yrs.)	□ N/A	<b></b>	Built in 1991	То	mperature (F)	<b>_</b>	86	
Weather Conditions			Raining/Rain Recently		Snowing	H	Cov. By Snow	✓ Hot
Water - Service (Size)	N/A	П	1/2 "		5/8 "	$\square$	3/4 "	✓ 1 "
Water - Supply (Size)	□ N/A		1/2 "		5/8 "		3/4 "	· · 1"
Water Heater - (Gals)	□ N/A	$\square$	30		40 x 2	Π	50	2 x 40
Furnace (BTHU) x 1000	N/A	П	75		100 x 2	$\square$	125	88
Cooling (TONS)	N/A		2-3x2		3 - 4	Π	4 - 5	≪5
Electrical Service (amps)	□ N/A	$\square$	60	$\square$	100	$\square$	150	200
Electrical Panel (amps)	N/A		60	$\square$	100		150	200
Range/Oven (Type)	N/A		Electric	$\square$	Gas	$\square$	Combination	Other
Main Roof (# of Layers)	N/A		1	Ы	2	$\square$	3	Other
Main Roof (Est. Age)	N/A		18 + yr.	H	2 10 - 17 yr.	$\square$	5 - 9 yr.	<ul> <li>✓ 0 - 4 yr.</li> </ul>
2nd Roof (# of Layers)	N/A		1	$\exists$	2	$\square$	3 - 3 yi.	Other
2nd Roof (Est. Age)	N/A		18 + yr.		2 10 - 17 yr.	$\square$	5 - 9 yr.	<ul> <li>✓ 0 - 4 yr.</li> </ul>
Insualtion (Thickness)	N/A		3"	$\exists$	4 - 6 "		6 - 8 "	· 0 - 4 yr. √ 9 - 16 "
	<u> </u>		-					





Painted wood trim with wall paint at Master Bedroom ceiling.









Repair cracked drywall surface at: upper level hallway.

	Repair cracked drywall surface at: Column at the main entry area.





Repair cracked drywall surface at: Master Bedroom Ceiling





Attic -- Recommend to seal areas where the furnace flues are venting across the roof (found evidence of prior water penetration).





Retaining Walls -- Recommend to build a retaining wall at the front-right corner of the building (lots of soil erosion, surface right now is covered with mulch).



Exterior Walls -- Call an stucco contractor to provide further evaluation and repairs for the orange/corrosion spots at the stucco walls (check the entire perimeter please).



It appears that two wooden windows at the left and right sides of the exterior fireplace were ordered too short respect to the frame or a portion of the window at the exterior is missing.



Roof (Low elevation at the back of the hosue) -- Missing two shingles (the ones that go above the metal flashings).